WELDING ON MACHINES WITH ELECTRONIC CONTROLS

Toolbox Talks are designed to promote safety discussions and best practices on the jobsite. To see more Toolbox Talks, please visit cat.com/toolboxtalks

As with all machines with electronic controls, special care should be taken when welding on the machine. Here are some tips for welding machines with electronic controls.

GENERAL WARNINGS & TIPS

- Always wear proper personal protective equipment (PPE)
- Before welding around electronics, if possible, remove the electronics in that area to reduce or eliminate heat damage caused by the welding process
- Turn the battery disconnect switch to the OFF position and verify that the hazardous voltage indication lamp turns off
- Lock-out and tag out the machine
- Clamp the ground cable from the welder to the component that will be welded and place the clamp as close to the weld as possible
- Do not use electrical components (engine control module (ECM) or ECM sensors) or electrical component grounding points for grounding the welder
- Do not weld in wet areas or in the rain
- Always weld in a well ventilated area
- Keep your work area clear of anything flammable
- Do not use cables that are frayed, cracked or have bare spots in the insulation

Employee Participants:				

Discussion Date:

The material in this document is provided for informational purposes only and not as a comprehensive or exhaustive resource on this topic. This material has been compiled from a multitude of sources believed to be accurate; however Caternillar Inc. assumes no responsibility for the accuracy or currency of this information and encourages you to consult experts in this area for more information. In no event does the content of this document supersede any applicable local, state or federal statutes or regulations.

There are a lot of moving parts on the jobsite. To find a safety topic relevant to your operation, please visit cat.com/toolboxtalks.

