2019/09/04

A Special Instruction Is Now Available that Contains the Procedure for Inspection and Repair of Front Axle Parking Brake for Certain TH3510D, TH357D, and TH408D Telehandlers {3020} (M0107923)

SMCS - 3020 i07788556

Telehandler

TH3510D (S/N: TH21-UP; TH31-UP) TH357D (S/N: TD61-UP; TD71-UP) TH408D (S/N: TH41-UP; TH91-UP)

Poly 1008 rection and Reference: Special Instruction, M0107747, "Procedure for Inspection and Repair of Front Axle

Parking Brake for Certain TH3510D, TH357D, and TH408D Telehandlers"

The Special Instruction referenced above contains the procedure for inspection and repair of front axle parking brake is now available.

The new procedure has preventative action for repair before failure and repair after failure of 459-0424 Lever.

Green

The Special Instruction is available through the normal literature distribution system. The publication can also be found on the Caterpillar Service Information System (SIS).

PIP-10087702 2021/03/31 14:32:58+01:00 i07788556 © 2021 Caterpillar Inc. Caterpillar:

Confidential Green