HOW TO KEEP DRIVERS IN THEIR CABS

Toolbox Talks are designed to promote safety discussions and best practices on the jobsite. To see more Toolbox Talks, please visit cat.com/toolboxtalks.

Drivers outside of a cab in loading and unloading areas may be exposed to a variety of hazards that exist on mine property.

PREPARE FOR LOADING

- Make sure drivers complete the following tasks before entering the mine site:
 - Clean truck bed
 - Check tires
 - Inspect truck
 - Prepare tarp

LOAD PROPERLY

- Do not overload trucks
- Designate dump-off areas for drivers to remove excess material
- Ensure drivers tarp and trim the load outside of the loading area
- Stop loading activities if the driver is not in the vehicle

KEEP DRIVERS SAFE AND AWARE

- Before drivers enter mine property, inform them of hazards they may encounter if stepping outside of the cab is necessary
- · If climbing is necessary, ensure drivers use ladders and proper fall protection

The material in this document is provided for informational purposes only and not as a comprehensive or exhaustive resource on this topic. This material has been compiled from a multitude of sources believed to be accurate; however, Caterpillar Inc. assumes no responsibility for the accuracy or currency of this information and encourages you to consult experts in this area for more information. In no event does the content of this document supersede any applicable local, state or federal statutes or regulations.

There are a lot of moving parts on the jobsite. To find a safety topic relevant to your operation, please visit cat.com/toolboxtalks.



Discussion	Date:		

Employee Participants: