

Lip Seal for Turbochargers

Genuine Parts



Continuous Product Improvement

Lip Seal Upgrade

Keeping up to date on changes in the industry, and informing customers of product improvement to meet new operational conditions is a part of our commitment to your success.

Often, the needs for product improvements are only evident or discovered at sea, or during dry dock, where the cost of repair and replacement may be limited by time and capital.

Turbocharger overhaul, exchange cartridges and specialized services are part of the capabilities of our growing Caterpillar Motoren distributor network.

The new lip seal arrangement is a standard feature in the next generation turbochargers and the lip seal has proven its reliability and improved sealing function on many Cat[®] engines. In addition, a number of turbochargers have already been tested and modified on medium-speed engines (MSE) of the Cat[®] and MaK[™] brands engines to take advantage of the enhanced sealing arrangement.

You Get what You Pay for

Long term aftermarket support and quick availability to quality parts is critical for your business, often making the difference in uptime and staying profitable. Genuine MaK components are designed to function reliably as part of a complete system. Our products are therefore continuously improved to ensure that using MaK parts enhances engine performance, even under changing economic conditions.

Lip seal upgrades can be requested from Cat[®] approved and MaK authorized distributors who are OEM trained and equipped to carry out maintenance on specific turbocharger types.



The Impact and Proposed Solution

While engine performance is not affected, the lower operating speed of the turbocharger does not produce sufficient sealing air to the shaft seal and lubricating oil may leak past the piston ring into the area behind the turbine wheel.


To prevent this from occurring, a contact type seal, or lip seal can be introduced which is designed to overcome low load operating conditions. Compared to a piston ring, this solution ensures an effective seal during continuous slow steaming.

The turbocharger lip seal is specially designed with materials chosen to minimize wear to the running surfaces of the shaft, and has proven to have a long and reliable lifetime between major overhauls.

Upgrade to Existing Turbochargers

The upgrade of the turbocharger includes the turbine bearing housing and rotor shaft which both require replacement in a suitable exchange cartridge.

The solution is a more robust shaft seal which can improve the cleanliness of the engine, reduce lubricating oil losses and minimize occasional smoke due to oil leakage at low load.



With consequential wear and damages that could result in a catastrophic malfunction, if the condition is permitted to remain without due care, attention and modification.

The risk of oil leakage past the piston ring seal is increased, particularly at the turbine end.

Better Engineering, Parts, and Service. Better Solutions.

For the past 25 years, turbochargers have been one of the core technologies of modern marine diesel engine. The improvements to Original Equipment Manufacturer (OEM) components, designed, tested and manufactured according to Caterpillar specifications bring benefits to owners and operators over the life of the engine.

One of the results of changes to the voyage pattern of vessel operations has been lower ship speed or "slow steaming". This has meant an adjustment to many vessel operational profiles, which can have consequences for the reliable function of the engines, turbocharger and air system.

For many MaK engines operating under extended idling/low load conditions, or continuous slow steaming, the engine and turbocharger may benefit from an upgrade to an improved sealing arrangement.



Greater reliability maximizes your uptime and reduces Total Cost of Ownership (TCO). For this reason, we have developed a turbocharger cartridge upgrade which is offered as a factory guaranteed exchange through our authorized dealers. This includes the following: the turbine bearing housing and rotor shaft which both require replacement in a suitable exchange cartridge.

What's the Risk?

Oil leakage can rapidly lead to a significant accumulation of hard deposits between the bearing housing and the rear of the turbine.


Consequential wear or damages to the sealing area and back of the turbine wheel may result in major malfunction, if the conditions are permitted to persist.

Subsequent to recurring periods of extended low load operation, the risk of oil leakage past the piston ring seal is increased.



Original piston ring seal

The oil leakage can rapidly lead to a significant accumulation of hard deposits between the bearing housing and the rear of the turbine.



New lip seal arrangement

Why Insist on Genuine MaK Parts?

Lower Operating Cost

For many MSE engine owners and operators, the ability to run vessels safely at low speeds or continuously slow steaming is a major factor in reducing total operating expenditure.

Peace of Mind

MSE engines operating with genuine parts perform longer with fewer unplanned maintenance events or risk of failure.

Availability

All parts can be dispatched within 24 hours through our strategically located distribution center and delivered globally by our authorized distributors.

Quality

The quality material and stringent process controls ensure our products are durable and OEM guaranteed to offer long service life with minimal risk of failure.



Faster. Less Expensive. Damage-Free parts.

All of our genuine MaK parts are easily available via the dealer network

Services for the lifetime of your engine – when you choose Caterpillar, you get that and much more. Our global network of local and certified dealers is available to support you with solutions and genuine expertise. The network offers you consistent availability of genuine parts and services worldwide while contributing to meeting your environmental and operational goals.

To find your local dealer, please visit our Dealer Locator:

https://www.cat.com/en_US/by-industry/marine/mak-dealer-locator.html



Global dealer network

Caterpillar Motoren GmbH & Co.KG
Falckensteiner Str. 2
24159 Kiel/Germany

Phone: +49 431 3995 01
Telefax: +49 431 3995 2193

For more information please visit our website:
cat.com/marine

Subject to change without notice.
Leaflet No. 428 - 07.22 - e - L+S - AD
LEDM0170-02

© 2022 Caterpillar. All Rights Reserved. CAT, CATERPILLAR, LET'S DO THE WORK, their respective logos, "Caterpillar Corporate Yellow", the "Power Edge" and Cat "Modern Hex" trade dress as well as corporate and product identity used herein, are trademarks of Caterpillar and may not be used without permission.

Contact your local dealer:
https://www.cat.com/en_US/by-industry/marine/mak-dealer-locator.html

Visit us on Shipserv at:
<https://www.shipserv.com/brand/mak>

Check out our MaK LinkedIn page to stay up to date:
<https://www.linkedin.com/showcase/caterpillar-mak/>

