

1. Measure the length and width of the worktable.
2. If the exact worktable size is not listed, round up to the next larger size on the chart.
3. The chart below helps determine the number of pieces needed with the least number of seams.
4. Use the chart to the right to determine the combination of 5 packs or 8 packs needed.

# of pieces needed (From the chart above)	# of 5 packs (Stk# TC24/5)	# of 8 packs (Stk# TC24/8)
5 pc:	1	-
8 pc:	-	1
10 pc:	2	-
13 pc:	1	1
15 pc:	3	-
16 pc:	-	2
18 pc:	2	1
20 pc:	4	-
21 pc:	1	2
23 pc:	3	1
24 pc:	-	3



230 Meek Rd
 Gastonia, NC USA 28056
 800-343-4542
 FAX 800-554-0407

Updated on 7/6/09