

## **The Self-Adhesive Standard (Or Metric) Tape Measure**

High quality, precision metal tape measure with adhesive backing. Sticks to almost any clean, dry surface. Tape measure will be always handy-never lost. Inch (or centimeter) numbers can be run from left to right or visa versa by rotating the table rule end-for-end.

### **USES:**

- Mount on edge of portable work benches
- Stationary work tables
- Saw tables
- Drawing tables
- Complete workshop systems
- Sewing tables

### **DIRECTIONS:**

1. Surface must be clean, dry and vacuum any lint off cloth surfaces.
2. Positioning table rule is often made easier by beginning at the place on the work table where you want the numbers to start.
3. Measure area. Cut table rule with scissors if necessary to shorten to less than 20 feet.
4. Peel off backing paper and press in place. Do not move table rule after applying to surface.