

Temperature Range:
-40° to 450°F
Rango de Temperatura:
-40° to 450°F (-40° to 267°C)



ACURITE®

Probe folds into handle for safe storage

La sonda se pliega en el mango para almacenamiento seguro

Easy-clean stainless steel probe

Fácil de limpiar sonda de acero inoxidable

Digital temperature reading in degrees Fahrenheit or Celsius

Lectura digital de la temperatura en grados Fahrenheit o Celsius

NSF certified

Certificado por NSF

USDA Recommended Internal Temperatures

Ground Meat/Poultry Mixtures

Turkey, Chicken (including Patties)..... 165°F/73.9°C
Veal, Beef, Lamb, Pork (including Patties).... 160°F/71.1°C

Fresh Beef / Veal / Lamb

Medium Rare 145°F/62.7°C
Medium 160°F/71.1°C
Well Done..... 170°F/76.6°C

Fresh Pork

Medium 160°F/71.1°C
Well Done..... 170°F/76.6°C

Poultry

Chicken & Turkey (whole)..... 165°F/73.9°C
Roasts & Breasts 165°F/73.9°C
Thighs & Wings 165°F/73.9°C
Duck & Goose 165°F/73.9°C

Ham

Fresh (raw)..... 160°F/71.1°C
Pre-Cooked (to reheat) 140°F/60.0°C

Care instructions: Wipe with damp cloth.

Instrucciones de lavado: Limpielo con un paño húmeda.

⚠ WARNING:

DO NOT wipe or handle hot thermometer with wet cloth. **DO NOT** lay hot thermometer on cold or wet surface. **DO NOT** heat beyond thermometer's temperature capacity. **DO NOT** use in oven. **DO NOT** wash in dishwasher. **DO NOT** submerge in water.

⚠ ADVERTENCIA:

NO frote o sujete el termómetro caliente con un paño húmedo. **NO** coloque el termómetro caliente sobre superficies frías o húmedas. **NO** caliente el termómetro más allá de su capacidad de temperatura ya que el tubo se puede romper.


Product Facts

Battery: 1 AAA (not included)

Measurement Ranges

Temperature: **-40°F to 450°F**
-40°C to 267°C

model 00665E



MADE IN CHINA
HECHO EN CHINA
Limited One
Year Warranty
Instructions &
Warranty Enclosed

Customer Care:
877-221-1252

www.AcuRite.com

AcuRite is a registered trademark of the
Chaney Instrument Co.
965 Wells St. • Lake Geneva, WI 53147